

ULTRASOUND TRANSDUCERS REPAIR / REPLACE



Cuts / Holes on the Lens



Housing Cracks



Gel Issue



Probe Oil Leakage



Air Gaps / Swelling
Membrane



Housing Gap

ULTRASOUND TRANSDUCERS REPAIR / REPLACE




Dried Out Lens



Housing Cracks

Visual Inspection of Ultrasound Transducers

- Conduct a Daily or Weekly detailed visual inspection of your probes
- Never ignore the minor issues such as small cuts / tears in your ultrasound transducers.
- Inspect for the following : Holes, Cracks, Cuts , Oil leakage
- Evaluating the quality of the scan image is a must . Look out for Dropouts, Noise , Artifacts, Coloured artifacts,




Artifact in Image




Noise in Image

ULTRASOUND TRANSDUCERS REPAIR / REPLACE



Colour Artifact



Crystal Probe Issue

- Getting your probes into the hands of experienced team of service providers can aid you in the full evaluation of the probe's condition.